

Moneris DX8000 & PAX A920 - Direct (Counter Integration)

*Procédure copier du Zoho de Cluster


NOTE: POS must be on 6.10.0.0 minimum for integration to work.

Works with DX8005 also! It has been tested.

Open the **Moneris** GO App




If it's Not there, you can install it from the PAXSTORE




On this page, the client must enter their **Moneris** Portal Credentials in order to Access General Settings, Tips settings or Standalone mode.


This will be their email and password they set up via the "Let's Get Started" email sent to them by **Moneris**.



It'll bring you to this Page where they can make payments in Standalone mode, Press the 3 Lines on top left.




Press Settings




From here, you can setup Receipt, Tips, Tax and many settings.


Press Sync once completed.



Once done, Sign Out




On this screen, press the X. If there's no X, press the Circle Home Button at bottom of screen.



Open the Go Integrated App




From this screen, swipe from Left to Right in order to access Quick Service Settings




Default Password is 212324

Press Settings




Set Operational Mode to Direct




Then Press Wifi


Make sure you're Connected to the same Wifi as the POS



Press and hold on the Wifi Name and tap Modify Network




Check Advanced Settings, Scroll down, and set IP Settings to Static




Configure the Terminal's IP, Gateway, DNS, etc


And Save



If back on this screen, Press Save



After tapping SAVE, you may see this screen:



The client will need to enter their **Moneris** MID.

If they do not have it, you will need to contact **Moneris** with the client.

You should be back to the Quick Service Page



On POS Settings, Device

Set **MONERIS** Device, Set IP of the Terminal

Payment Processing

Payment Processing

Devices Settings - 909b4f7f-f9cc-4b40-8a03-9a518643708f

Sub-Type

MONERIS

Interface

Network

IP/Host

10.100.50.50

Port

1180

Protocol

Moneris Go Integrated

Active

Test by sending a Payment

If POS freezes, reboot and it should be good to go!

Revision #2

Created 2026-06-03 18:02:05 UTC by simon

Updated 2026-06-03 18:14:32 UTC by simon